National Archives and Records Administration

Office of the Federal Register

ANE
NM
CE
SW

January 18, 2008

Ms. Nancy Molitor
Regulations Division (AGC-200)
Office of the Chief Counsel
Federal Aviation Administration, DOT
800 Independence Avenue, SW
Washington, DC 20591

Dear Ms. Molitor:

The material listed in the attachment is approved for incorporation by reference in 14 CFR Part 39.

This approval is contingent upon the final rule containing any language changes, which were agreed upon by our staffs. The approval to incorporate by reference this publication(s) is effective on the effective date of your final rule. If you wish to enforce some other edition of the publication(s) approved, you must:

1. Publish notice of the change in the Federal Register, and amend the Code of Federal Regulations; and

2. Ensure that a copy of that edition is on file at the Office of the Federal Register; and

3. Notify me in writing of the change.

Sincerely,

RAYMOND A. MOSLEY
Director of the Federal Register

Federal Register Attorney: AK

Attachment

U.S. mail address: 8601 Adelphi Road, College Park, MD 20740-6001
Office location: 800 North Capitol Street, NW, Suite 700, Washington, DC 20002-4244
Federal Register web sites: http://www.archives.gov/federal-register *and* http://www.gpoaccess.gov/nara

Incorporation by Reference

FAA Docket No. 2007-0053; Directorate ID 98-ANE-54-AD; Amdt. 39-15347; AD 2008-02-17

Middle River Aircraft Systems	Alert Service Bulletin CF6-50 S/B 78A3001	Revision 4	08/30/2007
Middle River Aircraft Systems	Alert Service Bulletin CF6-80A1/A3 S/B 78A1002	Revision 5	07/19/2007
Middle River Aircraft Systems	Alert Service Bulletin CF6-80C2A1/A2/A3/A5/A8/A5F S/B 78A1015	Revision 7	08/30/2007

FAA Docket No. 2007-28375; Directorate ID 2007-NM-015-AD; Amdt. 39-15346; AD 2008-02-16

Boeing Commercial Airplanes	Service Bulletin 767-21A0167	Revision 1	12/19/2006

FAA Docket No. 2007-28884; Directorate ID 2007-NM-116-AD; Amdt. 39-15343; AD 2008-02-13

Boeing Commercial Airplanes	Alert Service Bulletin 727-53A0224		04/10/2003

FAA Docket No. 2007-28973; Directorate ID 2007-NM-118-AD; Amdt. 39-15344; AD 2008-02-14

Boeing Commercial Airplanes	Alert Service Bulletin 747-33A2280	Revision 1	09/25/2003
Boeing Commercial Airplanes	Alert service Bulletin 757-33A0044	Revision 1	09/25/2003
Boeing Commercial Airplanes	Alert Service Bulletin 757-33A0045	Revision 1	09/25/2003
Boeing Commercial Airplanes	Alert Service Bulletin 767-33A0087	Revision 1	09/25/2003
Boeing Commercial Airplanes	Alert Service Bulletin 767-33A0088		12/19/2001

FAA Docket No. 2007-29170; Directorate ID 2007-NM-075-AD; Amdt. 39-15345; AD 2008-02-15

Airbus A318/A319/A320/A321	Mandatory Service Bulletin A320-57-1129	Revision 2	07/17/2007
Airbus A318/A319/A320/A321	Mandatory Service Bulletin A32-57-1130	Revision 2	07/17/2007
Airbus A318/A319/A320/A321	Service Bulletin A320-57-1131		11/21/2006

Incorporation by Reference

Airbus A318/A319/A320/A321	Service Bulletin A320-57-1137		11/21/2006
Airbus A318/A319/A320/A321	Service Bulletin A320-57-1140		11/21/2006

FAA Docket No. 2007-29317; Directorate ID 2007-CE-079-AD; Amdt. 39-15348; AD 2008-02-18

Ballistic Recovery Systems	Service Bulletin 07-01		06/08/2007
Ballistic Recovery Systems	Service Bulletin 07-02		06/08/2007

FAA Docket No. 2007-29329; Directorate ID 2007-NM-205-AD; Amdt. 39-15342; AD 2008-02-12

Boeing Commercial Airplanes	Service Bulletin 717-28-0007	Revision 1	09/23/2003

FAA Docket No. 2008-0043; Directorate ID 2007-SW-31-AD; Amdt. 39-15340; AD 2008-02-10

Eurocopter	Emergency Alert Service Bulletin 67.00.29	Revision 1	04/27/2007

FAA Docket No. 2008-0044; Directorate ID 2007-SW-40-AD; Amdt. 39-15341; AD 2008-02-11

Eurocopter	Emergency Alert Service Bulletin 67.00.36		10/09/2006