



U.S. Department of Labor
Occupational Safety & Health Administration

www.osha.gov

Search

[Advanced Search](#) | [A-Z Index](#)

Accident Search Detail

Accident 000603621 - Employee on Bicycle Killed in Bus Collision

Accident 000603621 -- Report ID: 0419400 -- Event Date: 08/05/1994

Inspection: 018130112 Open: 08/09/1994 SIC: 3731 Ingalls Shipbuilding Inc.

Employee #1 was riding a bicycle south on the main roadway at the intersection of the thermal coating building bus traveling north on the same roadway stopped to make a left turn at the intersection in order to head west. The bicycle and the front left side of the bus collided, knocking Employee #1 to the pavement. He died. Employee #1 was performing his regularly assigned tasks.

Review: E Keywords: collision,bus,

Inspection Age Sex Degree Nature Occupation

1 018130112 52 M Fatality Fracture Electricians

[Back to Top](#)

www.osha.gov

[www](#)

[Contact Us](#) | [Freedom of Information Act](#) | [Information Quality](#) | [Customer Survey](#)
[Privacy and Security Statement](#) | [Disclaimers](#)

Occupational Safety & Health Administration
200 Constitution Avenue, NW
Washington, DC 20210