

The Boeing Company  
P.O. Box 3707  
Seattle, WA 98124-2207

January 6, 2009

B-H210-09-00005

Docket Management Facility  
U.S. Department of Transportation  
400 Seventh Street SW  
Nassif Building, Room PL-401  
Washington, DC 20590  
Attention: Airworthiness Rules Docket No. FAA-2008-1131

**Subject: Comments, NPRM Docket No. FAA-2008-1131 (Directorate Identifier 2008-NE-37-AD): "Inspecting All High Pressure Turbine (HPT) 2<sup>nd</sup> Stage Hubs at the Next HPT Overhaul", Airplane Model 757**

Boeing has reviewed the subject NPRM and concurs with the contents of the proposed rule. Therefore, no additional comments will be forthcoming.

Very truly yours,

*G. K. Dial*

*for*  
G. K. Dial *1.6.09*  
Manager, Continued Airworthiness  
Single Aisle Programs  
B-H210, MC 67-TC, (425) 237-9472  
FAX: (425) 234-4649

jam

