



Albert Mercado/ACE/FAA
ACE-112, Project Support
Branch

10/21/2008 09:46 AM

To Scott Wessley/ACE/FAA@FAA
cc David R Showers/ACE/FAA@FAA, Jacqueline
Jambor/ACE/FAA@FAA, Tammy Coffman/ACE/FAA@FAA
bcc

Subject Re: Immeidately Adopted Rule (IAR) on Socata TBM 700
pulley drive assembly

Scott,

I have reviewed the comment received by Mr. Benischeck. His comments relate to clarifying to the serial numbers involved and does not provide any new data or data that would influence the FAA's reconsideration of the published AD.

As directed below, please insert the following statement in the document.

"The comments contained in this docket, No. FAA-2008-0974, have been reviewed by the FAA and have not been found to contain any information to warrant reconsideration or revision of this airworthiness directive."

Thanks,

Albert J. Mercado
Federal Aviation Administration
Small Airplane Directorate, ACE-111
901 Locust Street, Room 301
Kansas City, MO 64106
phone: 816-329-4119
fax: 816-329-4090
email: albert.mercado@faa.gov
Scott Wessley/ACE/FAA

Scott Wessley/ACE/FAA
ACE-113, Continued
Operational Safety Branch

10/21/2008 09:27 AM

To Albert Mercado/ACE/FAA@FAA
cc David R Showers/ACE/FAA@FAA, Jacqueline
Jambor/ACE/FAA@FAA, Tammy Coffman/ACE/FAA@FAA
Subject Immeidately Adopted Rule (IAR) on Socata TBM 700 pulley
drive assembly

Albert

The comment period for your immediately adopted rule (IAR) AD action, Docket No. FAA-2008-0974; DI: 2008-CE-048-AD, closed on October 20, 2008.

Section 70.a.(5)(b) of Airworthiness Directives Manual, dated May 28, 2008, FAA-IR-M-8-40.1B (FAA-AIR-M-8040.1) states the following:

"Comments received in response to an immediately adopted rule) including follow-up publication in an Emergency AD).

1 If the comments provide no new data or data that would influence the FAA's reconsideration of the published AD in any wy, no further publication action is necessary to dispose of these comments. However, to assure the public that these comments after a final rule have been considered fairly, the

following statement should be inserted in the docket after the comment period has closed and comments have been analyzed:

"The comments contained in this docket, No. XX-XX-XX, have been reviewed by the FAA and have not been found to contain any information to warrant reconsideration or revision of this airworthiness directive."

Please go to the docket and review any comments. If the above applies, either prepare a memo or send an e-mail. If you choose the e-mail, please note that a copy of the e-mail will be scanned and placed in the docket.

<http://www.regulations.gov/fdmspublic/component/main?main=DocketDetail&d=FAA-2008-0974>

Thanks

Scott Wessley
AD Coordinator
Small Airplane Directorate
(816) 329-4148